

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	04/06/2017 04/06/2017	Sterling York

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_ST0006_01_s _ 2014_9				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard has copies of the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_ST0006_01_s _ 2014_10				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard has flood fight supplies on hand at their equipment yard.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	04/06/2017 04/06/2017	Sterling York

LM Start		Rating **	A	Issue No.	11
LM End		Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				o
					o
DWR ID	DWR_ST0006_01_s_2014_11				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard has attended flood fight training.					

No Photos

LM Start	0.02	Rating **	U	Issue No.	15
LM End	0.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.886883 °	38.881287 °
				-121.614797 °	-121.614490 °
DWR ID	DWR_ST0006_01_f_2015_15				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the vegetation and trim up the trees 5 feet for visibility.					

Photo 1 of 1 : SP_2017_ST0006_471_15_20170410_00008.jpg



View of the vegetation along the waterside slope looking downstream.
Spring 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	04/06/2017 04/06/2017	Sterling York

LM Start	0.02	Rating **	U	Issue No.	2
LM End	0.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.886883 °	38.880833 °
				-121.614797 °	-121.614387 °
DWR ID	DWR_ST0006_01_f_2015_2				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the vegetation, wild growth, and trim up the trees 5 feet for visibility.					

Photo 1 of 1 : SP_2017_ST0006_471_2_20170410_00007.jpg



View of the vegetation along the landside slope looking downstream. Spring 2017.

LM Start	0.06	Rating **	M	Issue No.	4
LM End	0.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.886277 °	38.886277 °
				-121.615129 °	-121.615129 °
DWR ID	DWR_ST0006_01_s_2012_4				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

Photo 1 of 1 : SP_2017_ST0006_471_4_20170316_00002.jpg



View of the elderberries that are blocking visibility.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	04/06/2017 04/06/2017	Sterling York

LM Start	0.15	Rating **	M	Issue No.	5
LM End	0.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.885100 °	38.885100 °
				-121.615722 °	-121.615722 °
DWR ID	DWR_ST0006_01_s _ 2012_5				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

LM Start	0.16	Rating **	M	Issue No.	12
LM End	0.16	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.884946 °	38.884946 °
				-121.615761 °	-121.615761 °
DWR ID	DWR_ST0006_01_s _ 2015_12				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

LM Start	0.18	Rating **	M	Issue No.	13
LM End	0.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.884577 °	38.884577 °
				-121.615761 °	-121.615761 °
DWR ID	DWR_ST0006_01_s _ 2015_13				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2017

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	04/06/2017 04/06/2017	Sterling York

LM Start	0.21	Rating **	M	Issue No.	14
LM End	0.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.884151 °	38.884151 °
				-121.615732 °	-121.615732 °
DWR ID	DWR_ST0006_01_s _ 2015_14				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

LM Start	0.34	Rating **	M	Issue No.	6
LM End	0.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.882398 °	38.882398 °
				-121.614966 °	-121.614966 °
DWR ID	DWR_ST0006_01_s _ 2012_6				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---